



public works

Department:
Public Works
REPUBLIC OF SOUTH AFRICA

Private Bag X54315, Durban, 4000, Tel (031) 314 7000
Corner of West and Aliwal Streets, Durban

From: NATIONAL DEPARTMENT OF PUBLIC WORKS
Tel: 072 6124797 / (031) 314 7046
Enquiries: Mr N Moloto / Anora Singh Ref: DBNQ-ID3281562

ERRATUM NOTICE FOR : DBNQ-ID3281562 That was advertised on the Departmental website on the 14/07/2026 without a Site Inspection/Visit control form

DBNQ-ID3281562: OTHER: JL DUBE HOUSE (KINGS HOUSE): SERVICE AND REPAIR FIRE CONTROL PANEL AND GAS SUPPRESSION:

PLEASE NOTE THAT DBNQ-ID3281562 WAS ADVERTISED WITHOUT A SITE INSPECTION/VISIT CONTROL FORM ON THE DEPARTMENTAL WEBSITE

**TENDERERS MUST TAKE NOTE OF" DBNQ-ID3281562 is still on the website
ORIGINAL ADVERT DATE: 14/07/2026**

ERRATUM CLOSING DATE: 20/07/2026

**Supply Chain Management
For: REGIONAL MANAGER**

Lefapha la Ditiro tsa Setshaba Department of Public Works Lefapha la Mesebetsi ya Setshaba Kgoro ya Mésomo ya Setshaba Ndzawuloya Mintirho ya Vaaki LiTiko leTemisebenti
yaHulumende Yomphakatsi ISebe leMisebenzi yoluNtu UmNyango wezemiSebenzi yomPhakathi uMnyango Wemisebenzi Yomphakathi eMiphakathi Muhasho wa Mishumo ya
Tshitshavha Departement van Openbare Werke



public works
& infrastructure

Department:
Public Works and Infrastructure
REPUBLIC OF SOUTH AFRICA

SITE INSPECTION/VISIT CONTROL FORM

Client Department: **THE PRESIDENCY**

Complex Description: **KINGS HOUSE**

Service Description: **CHECK AND REPAIR FIRE CONTROL PANEL AND GAS SUPPRESSION.**

ID NUMBER: **3281562**

Planned Completion: **Thirty days from appointment**

Site Inspection: **Detail overview of work to be done**

COMPANY INFORMATION

Service Provider Name: _____

Represented by: _____

Signature: _____

CLIENT DEPARTMENT

Represented by: _____

Rank: _____

Signature: _____

Contact Details: _____

CLIENT STAMP

--